

Emitido em: 13/01/2018 10:16

BICO INJEÇÃO DIRETA

AUDI



 BOSCH	0261500026 A32.0 FSI05>
	

06F906036D

 BOSCH	0261500162059076 A32.0 TSFI08> A4 A6
	

0261500076

 BOSCH	0261500350 A31.4 TFSI12>
	

04E906036Q

BMW



 BOSCH	0261500073494 116I1.6 16V THP12>15 316I1.6 16V THP12>15
	

13537591623

 BOSCH	0261500109 BMW BMW 528I2.012> BMW X 5 XDRIVE 35I3.01 BMW X1 XDRIVE 28I2.813 BMW X3 XDRIVE 28I2.813 BMW X63.012>
	

13647597870

 BOSCH	0261500172 320 I GT XDRIVE3.0 GAS 320 I XDRIVE3.0 GASOLI 320I3.0 GASOLINA13>15 328 I XDRIVE3.0 GASOLI 420 I CABRIO3.0.GASOLI 528 I XDRIVE3.0 GASOLI 535 I3.0 GASOLINA15>15
	

13647639994

 BOSCH	0261500260 BMW X12.0 E8411>15 BMW X1 XDRIVE 28I2.8 E BMW X3 XDRIVE 20I2.0 F
	

13648625397

CITROEN



 BOSCH	0261500073494 C4 LOUNGE1.6 16V THP13 C51.6 16V THP11> DS31.6 16V THP12>15 DS41.6 16V THP11> DS51.6 16V THP11>
	

1984 H5

MINI-COOPER





BOSCH

0261500073494

COOPER S 1.6 16V THP10
COOPER S CABRIO1.6 16V
COOPER S
COOPER S COUPE1.6 16V
COOPER S ROADSTER1.6 1
JOHN COOPER WORKS1.6 1



13537591623

PEUGEOT



BOSCH

0261500073494

30081.6 16V THP9>
3081.6 16V THP12>
4081.6 16V THP12>
5081.6i 16V THP11>
RCZ1.6 16V THP11>



1984 H5

VOLVO



BOSCH

0261500103

S6010>
S8010>
V6010>
V7010>
VOLVO10>



BM5G9F593BB

VW



BOSCH

0261500020

JETTA 2.0 FSI
PASSAT 2.0 FSI
TIGUAN 2.0 TSI



06F906036A



BOSCH

0261500026

GOLF2.0 FSI05>
PASSAT2.0



06F906036D



BOSCH

0261500162059076

AMAROKTSI
FUSCA2.0 TSI
JETTA2.0 TSFI08>
PASSAT2.0 TSFI08>
TIGUAN2.0 TSFI08>



06H906036P



BOSCH

0261500350

GOLF 1.4 TSFI1.4 TFSI1
UP 1.0 TSI1.0 3CC FLEX



04E906036Q